

Safety Data Sheet (SDS)

Johnson Abrasiveś

Crocus Cloth

Revision Date: 6/28/2017 MSDS Number: 158

Page 1 of 8

PRODUCT AND COMPANY IDENTIFICATION

Manufacturer

Johnson Abrasives 49 Fltzgerald Drive Jaffrey, NH 03452

Contact: Johnson Abrasives Phone: +1-603-532-4434 +1-603-532-4436 Fax:

Web: www.johnsonabrasives.com

Crocus Cloth **Product Name: Revision Date:** 6/28/2017

Version: **MSDS Number:** 158 **CAS Number: MIXTURE Product Use: Abrasive Product**

Emergency Phone: +1-800-642-4265 or +1-603-532-4434

HAZARDS IDENTIFICATION

NFPA: HMIS III:

2



Health = 1, Fire = 0, Reactivity = 0 H*1/F0/PH0



PERSONAL PROTECTION INDEX G 🗷 + 🗯 + 💥 Ø Ø + 🗲 C 🖣 + 🗲 + 🏌 + 👢 Consult your superviso or S.O.P. for "SPECIAL" handling directions

GHS Signal Word: WARNING

GHS Classifications:

Health, Skin corrosion/irritation, 3

Health, Serious Eye Damage/Eye Irritation, 2 B

GHS Phrases:

H316 - Causes mild skin irritation

H320 - Causes eye irritation

GHS Precautionary Statements:

P261 - Avoid breathing dust produced while using this product.



Crocus Cloth

MSDS Number: 158 Revision Date: 6/28/2017

Page 2 of 8

P264 - Wash face, hands and any exposed skin thoroughly after handling.

P271 - Use only outdoors or in a well-ventilated area.

P280 - Wear protective gloves/protective clothing/eye protection/face protection.

P285 - In case of inadequate ventilation wear respiratory protection.

P302+352 - IF ON SKIN: Wash with soap and water.

P304+341 - IF INHALED: If breathing is difficult, remove victim to fresh air and keep at rest in a position comfortable for breathing.

P305+351+338 - IF IN EYES: Do NOT rub. Rinse continuously with water for several minutes. Remove contact lenses if present and easy to do. Continue rinsing.

P332+313 - If skin irritation occurs: Get medical advice/attention.

P337+313 - If eye irritation persists: Get medical advice/attention.

P342 - If experiencing respiratory symptoms: Get medical advice/attention.

P402 - Store in a dry place.

3

COMPOSITION/INFORMATION ON INGREDIENTS

Ingredients:

Cas #	Percentage	Chemical Name
N/A	45-55%	Cloth or Paper
N/A	10-30%	Animal Glue Bond
1309-37-1	15-25%	Iron Oxide (Fe2O3)

4 FIRST AID MEASURES

Inhalation: Blow nose to remove substance from nasal passages. Give oxygen or artificial respiration if needed. If

symptoms develop, move victim to fresh air. If symptoms persist, obtain medical attention.

Skin Contact: No need for first aid is anticipated for non-abrasive exposure to product. If reddening develops and/or

persists, obtain medical attention.

Eye Contact: Do NOT rub eyes. Flush with large amounts of water for at least 15 minutes, lifting upper and lower lids

occasionally. If irritation persists, obtain medical attention.

Ingestion: No need for first aid is anticipated. If symptoms develop, obtain medical attention.

Most important symptoms and effects, both acute and delayed:

The most important known symptoms and effects are described in the labelling (see Section 2) and/or Section 11.

Prolonged inhalation of Iron Oxide (Fe2O3) dust may result in siderosis. Siderosis is considered to be a benign pneumoconiosis and does not normally cause significant physiological impairment. Siderosis can be observed in x-rays with the lungs having a mottled appearance.

Indication of any immediate medical attention and special treatment needed:

No data available.



Crocus Cloth

MSDS Number: 158 Revision Date: 6/28/2017

Page 3 of 8

5

FIRE FIGHTING MEASURES

Flammability: Not classified

Flash Point: DNA Flash Point Method: DNA

Burning Rate: No data available
Autoignition Temp: No data available

LEL: DNA UEL: DNA

Product is flammable when exposed to direct flame. During proper, recommended use of this product, no flammability hazard exists.

Extinguishing Media:

Water Spray
Carbon Dioxide
Alcohol-Resistant Foam
Dry Chemical

Special Hazards Arising From the Substance or Mixture:

Carbon Oxides Iron Oxides Silicon Oxides

Advice for Firefighters:

Firefighters should wear full-face, positive-pressure respirators.

Further Information:

If incinerated, may release toxic fumes.

See Section 7 for more information on safe handling.

See Section 8 for more information on personal protection equipment.

6

ACCIDENTAL RELEASE MEASURES

Personal precautions, protective equipment and emergency procedures:

Use personal protective equipment, including dust respirator.

Avoid breathing dust.

Ensure adequate ventilation.

Environmental precautions:

No special environmental precautions required.

Methods and materials for containments and cleaning up:

Pick up and arrange disposal without creating dust.

Sweep up, shovel or collect spillage and place material into suitable container for disposal.

Inspect product for torn or damaged areas. Do not use if product is torn or damaged.

Dispose of contaminated material according to Section 13.

Ensure adequate ventilation.

Reference to other sections:

See Section 7 for information on safe handling.



Crocus Cloth

MSDS Number: 158 Revision Date: 6/28/2017

Page 4 of 8

See Section 8 for information on personal protection equipment.

See Section 13 for information on proper disposal.

HANDLING AND STORAGE

Handling Precautions: Ensure adequate ventilation.

Avoid breathing of dust created while sanding, grinding or machining - use dust respirator

while using product.

Avoid contact with skin, eyes and clothing.

Damaged product can break apart during use and cause serious bodily injury, specifically to

the eyes - use safety glasses while using product.

Check product for damages such as tears or cracks prior to use. Do not use damaged

product.

Comply with RPM rating specified on this product.

Comply with ANSI B7.1-2010 Safety Requirements for the Use, Care and Protection of

Abrasive Wheels (if applicable).

Combustible dust may be formed as a result of using this product. Take care to not let

generated dust accumulate.

Accumulated dust may present an explosive hazard when dispersed in sufficient

concentration while near an ignition source.

Collect dust and dispose of regularly.

Storage Requirements: Keep away from heat, sparks and flames.

Store in a dry place - keep away from moisture.

Store at temperatures between 40-90 °F at 30-80% relative humidity.

Store away from strong acids, strong oxidizing agents, Chloroformates and Hydrogen

Fluoride.

EXPOSURE CONTROLS/PERSONAL PROTECTION

Engineering Controls: All ventilation should be designed in accordance with OSHA standard (29 CFR 1910.94). Use

local exhaust at filling zones and where leakage and dust formation is probable. Use

mechanical (general) ventilation for storage areas. Use appropriate ventilation as required to

keep Exposure Limits in Air below TLV & PEL limits.

Personal Protective Equip: Eye/face protection:

When using material use safety glasses, gloves, and dust respirator according to HMIS PP, E.

All safety equipment should be tested and approved under appropriate government standards

such as NIOSH (US) or EN 166 (EU).

Skin protection:

Handling material with gloves is not required, but strongly recommended in order to prevent accidental secondary contact with eyes. Gloves must be inspected prior to use. Use proper

glove removal technique (without touching glove's outer surface) to avoid skin contact.

Dispose of contaminated gloves according to applicable laws and practices.

Body Protection:

Safety glasses, gloves and dust respirator are recommended. Type of protective equipment should be selected based on ventilation conditions and other conditions of use of this material.

Respiratory protection:

Use a NIOSH/MSHA dust mask according to 24 CFR 1910.134. Full-face dust respirator may be required as backup to engineering controls when proper engineering controls are not in



Odorless

Crocus Cloth

MSDS Number: 158 Revision Date: 6/28/2017

Page 5 of 8

place to keep TLV and PEL limits below defined thresholds.

Control of environmental exposure: No special requirements are necessary.

Components with workplace control parameters:

Component(s): Animal Glue Bond; Iron Oxide (Fe2O3)

CAS No(s): N/A; 1309-37-1

Physical State:

USA OSHA Occupational Exposure Limits Table Z-1 Limits for Air Contaminant (TWA): 15.0 mg/m³ (as total dust)

USA OSHA Occupational Exposure Limits Table Z-1 Limits for Air Contaminant (TWA): 5.0 mg/m³ (as respirable fraction)

USA OSHA Table Z-1 Limits for Air Contaminants - 1910-1000 (TWA): 10.0 mg/m³ (as total dust)

USA OSHA Table Z-1 Limits for Air Contaminants - 1910-1000 (TWA): 5.0 mg/m³ (as respirable fraction)

USA ACGIH (TWA/TLV): 0.025 mg/m3

USA NIOSH (TWA): 10.0 mg/m³ (as total dust)

USA NIOSH (TWA): 5.0 mg/m³ (as respirable fraction)

Solid

Biological occupational exposure limits:

Contains no substances with biological occupational exposure limits values.

9 PHYSICAL AND CHEMICAL PROPERTIES

Appearance: Cloth or paper coated with abrasive material

Odor Threshold: DNA **MIXTURE** Molecular Formula: DNA **Particle Size:** Solubility: DNA Spec Grav./Density: DNA **Softening Point:** DNA Percent Volatile: Viscosity: DNA DNA Sat. Vap. Conc.: DNA **Heat Value:** DNA **Boiling Point:** Freezing/Melting Pt.: DNA DNA (solid, gas): Not classified Flash Point: DNA Flammability: Partition Coefficient: DNA Octanol: DNA **Vapor Pressure:** DNA **Vapor Density:** DNA pH: DNA VOC: DNA Evap. Rate: DNA **Bulk Density:** DNA Molecular weight: DNA Auto-Ignition Temp: DNA **Decomp Temp:** DNA UFL/LFL: DNA

10 STABILITY AND REACTIVITY

Stability: Product is stable under normal conditions.

Conditions to Avoid: Incompatibilities, flames, ignition sources and moisture.

Materials to Avoid: Strong acids, strong oxidizing agents, Chloroformates and Hydrogen Fluoride.

Hazardous Decomposition: Carbon Oxides, Iron Oxides and Silicon Oxides.

Hazardous Polymerization: Will not occur.



Crocus Cloth

MSDS Number: 158 Revision Date: 6/28/2017

Page 6 of 8

11

TOXICOLOGICAL INFORMATION

Component(s): Iron Oxide (Fe2O3)

CAS No(s): 1309-37-1

Acute Toxicity:

LDLo Intratracheal - Rat: 200 mg/kg LDLo Intravenous - Rat: 90 mg/kg LDLo Intravenous - Mouse: 40 mg/kg

LCLo Inhalation - Rat: 0.500 mg/m³ (24 h, Iron Oxide (Fe2O3))

Skin Corrosion/Irritation: Skin - Human: Causes irritation. Mechanical irritation (abrasion) may also cause skin irritation.

Serious Eye Damage/Eye Irritation: The product itself does no present hazards. Dust created by grinding, sanding or machining may cause eye irritation.

Respiratory or Skin Sensitation: No data available.

Germ Cell Mutagenicity: No data available.

Carcinogenicity: This product is or contains a component that is not classifiable as to its carcinogenicity by the IARC, ACGIH, NTP or OSHA (Iron Oxide (Fe2O3)). Iron Oxide (Fe2O3) is shown to be an equivocal tumorigenic agent by RTECS criteria (causing tumors at site or application) in rats via subcutaneous exposures.

IARC: 3 - Group 3: Not classifiable as to its carcinogenicity to humans (Iron Oxide (Fe2O3)).

ACGIH: No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or

potential carcinogen by ACGIH.

No component of this product present at levels greater than or equal to 0.1% is identified as a carcinogen or OSHA: potential carcinogen by OSHA.

Reproductive Toxicity: No data available.

Specific Target Organ Toxicity - Single Exposure: Respiratory system: The product itself does no present hazards. Dust created by grinding, sanding or machining may cause respiratory irritation.

Specific Target Organ Toxicity - Repeated Exposure: Respiratory system: May cause damage to the respiratory system through prolonged or repeated exposure.

Aspiration Hazard: No data available.

Additional Information:

Component: Iron Oxide (Fe2O3); RTECS: NO7400000



Crocus Cloth

MSDS Number: 158 Revision Date: 6/28/2017

Page 7 of 8

12

ECOLOGICAL INFORMATION

Component(s): Iron Oxide (Fe2O3)

CAS No(s): 1309-37-1

Toxicity:

Toxicity to fish: No data available.

Toxicity to daphnia and other aguatic invertebrates:

No data available.

Persistence and Degradability:

No data available.

Bioaccumulative potential:

No data available.

Mobility in Soil:

No data available.

Results of PBT and vPvB assessment:

Not required/conducted.

Other Adverse Effects:

An environmental hazard cannot be excluded in the event of unprofessional handling or disposal.

13

DISPOSAL CONSIDERATIONS

Product: Hazardous wastes shall be managed responsibly. All entities that store, transport or handle hazardous waste shall take the necessary measures to prevent risks of pollution, release into the environment or damage to people and animals. Contact a licensed professional waste disposal service to dispose of this material. Consult all applicable authorities and regulations to ensure proper classification. Any abraded material remaining on used product (from the substrate being abraded) may need to be considered as a factor in the disposal classification, method or handling of used product.

Contaminated Packaging: Dispose of as unused product.

14

TRANSPORT INFORMATION

DOT (US)

Non-regulated material

IMDG

Non-regulated material

IATA

Non-regulated material

IMO

Non-regulated material



Crocus Cloth

MSDS Number: 158 Revision Date: 6/28/2017

Page 8 of 8

15

REGULATORY INFORMATION

COMPONENT / (CAS/PERC) / CODES

*Iron Oxide (Fe2O3) (1309371 15-25%) MASS, NJHS, OSHAWAC, PA, SARA311/312, TSCA, TXAIR

REGULATORY KEY DESCRIPTIONS

MASS = MA Massachusetts Hazardous Substances List
NJHS = NJ Right-to-Know Hazardous Substances
NRC = Nationally Recognized Carcinogens
OSHAWAC = OSHA Workplace Air Contaminants
PA = PA Right-To-Know List of Hazardous Substances
PROP65 = CA Prop 65
SARA311/312 = SARA 311/312 Toxic Chemicals
TSCA = Toxic Substances Control Act
TXAIR = TX Air Contaminants with Health Effects Screening Level

16

OTHER INFORMATION

Disclaimer:

The data in this Safety Data Sheet relates only to the specific material designated herein and does not relate to use in combination with any other material in any process. The information set forth herein is furnished free of charge and is based on technical data that Johnson Abrasives believes to be reliable. It is intended for use by persons having technical skill and at their own discretion and risk. Since conditions of use are outside of Johnson Abrasives' control, Johnson Abrasives makes no warranties, expressed or implied, and assumes no liability in connection with any use of this information. Nothing herein is to be taken as a license to operate under, or a recommendation to infringe upon, any patents.

Preparation Information:

GHS Conversion Services www.ghsconversionservices.com (414) 336-2546 (669) 236-0304